



More information on the website
radwag.com/en/info,w1,MLB

Tare and Print External Buttons



The drawings, photos and graphics used are for illustrative purposes only.

Overview

Buttons for remote control of TARE and PRINT functions. The buttons are enclosed in a plastic housing, the unit features 1.5 m cable. PT0021 - (PUE C41H) PT0213 - (PUE 5.15, PUE 5.19, PUE HY10, PUEHX7) PT0188 - (PUE 7.1)

* Connects with an indicator equipped with 4in/out module on connectors.

Compatible with

HX7 H Stainless steel Multifunctional Scale
 HX7.4N H Multifunctional Stainless Steel Ramp Scale
 HX7.4C Multifunctional Platform Scale
 HX7 HR Multifunctional Scale
 WPY Multifunctional Scale
 C32 Multifunctional Scale
 HY10.HRP.H Stainless steel High Resolution Scale
 HX7.4P2 H Multifunctional Stainless Steel Beam Scales
 WLY Scales for PGC
 HX7.4N H.LD Multifunctional Stainless Steel Ramp Scale
 DWT/RC/HYF Checkweighers
 HX7.4P H Multifunctional Stainless Steel Pallet Scales
 HY10 Multifunctional Scale

HY10.HRP High Resolution Scale
 HX7 Multifunctional Scale
 HX7.4 H/Z Multifunctional Stainless Steel Platform Scale, pit version
 WPY Scales for PGC
 HX7.4 H Multifunctional Stainless Steel Platform Scale
 HX7.4P2 Multifunctional Beam Scales
 HY10.H Scales for PGC
 WLY Precision Balance
 PUE C32 Weighing Terminal
 PUE 7.1 Weighing Terminal
 PUE HX7 Weighing Terminal
 DWM H2 Checkweighers
 HX7.4P Multifunctional pallet scales

