



More information on the website
radwag.com/it/info,w1,D48

DWR 1500 H2 sistema automatico controllo peso

WK-104-2__



The drawings, photos and graphics used are for illustrative purposes only.

Specifiche

Parametri metrologici	
Portata massima [Max]	1500 – 7500 g
Divisione [d]	0,5 – 5 g
Campo di tara	-1500 – -7500 g
Parametri fisici	
Display	12" graphic colour touchscreen
Pressione operativa	6 – 8 bar
Costruzione	
Punteggio IP	IP 55, IP 65
Environmental conditions	
Ambiente di lavoro	0 – +40 °C
Air consumption	1 liter/measurement
Caratteristiche operative	
Capacità del database	max 160 pcs/min



Accessori (Additional Fee)

Lettore di tessere transponder
Cavo seriale RS 232 (connessione bilance - Stampanti ZEBRA)
Cavo seriale RS 232, RS 485

USB adapter
Stampanti di ricevuta
cavo USB (connessione bilance - stampanti)