



More information on the website
radwag.com/es/info,w1,G0J

Soporte para terminal PUE HY10 / PUE HX7 / PUE HX5.EX



The drawings, photos and graphics used are for illustrative purposes only.

Descripción

A stand, based on a tripod for supporting scale's indicator installed on a cable PUE HY10 / PUE HX7 / HX5.EX. Stainless steel version available.

Stand for measuring indicator PUE HX5.EX can only be purchased together with the HX5.EX indicator/ scale.

Trabaja con

Báscula multifuncional inoxidable HX7 H
Báscula con rampa Multifuncionale inoxidable HX7.4N H
Báscula multifuncionale de plataforma HX7.4C
Báscula multifuncional HX7 HR
Balanza de alta resolución inoxidables HY10.HRP.H
Básculas multifuncionales de patines inoxidables HX7.4P2 H
Báscula con rampa Multifuncionale inoxidables HX7.4N H.LD
Básculas multifuncionales para paletas inoxidables HX7.4P H
Báscula multifuncional HY10
Báscula multifuncionale inoxidable HY10 H

Balanza de alta resolución HY10.HRP
Báscula multifuncional HX7
Báscula multifuncionale de plataforma inoxidable hundidas HX7.4 H/Z
Báscula multifuncionale de plataforma inoxidable HX7.4 H
Básculas multifuncionales de patines HX7.4P2
Balanza HY10.H para CCE
Terminal de pesaje PUE HX7
Terminal de pesaje PUE HY10
Básculas multifuncionales para paletas HX7.4P

Dimensiones de aparato

