



More information on the website  
[radwag.com/es/info,w1,G0J](http://radwag.com/es/info,w1,G0J)

## Soporte para terminal PUE HY10 / PUE HX7 / PUE HX5.EX



The drawings, photos and graphics used are for illustrative purposes only.

### Descripción

A stand, based on a tripod for supporting scale's indicator installed on a cable PUE HY10 / PUE HX7 / HX5.EX. Stainless steel version available.

Stand for measuring indicator PUE HX5.EX can only be purchased together with the HX5.EX indicator/ scale.

### Trabaja con

Báscula multifuncional inoxidable HX7 H  
 Báscula con rampa Multifuncionale inoxidable HX7.4N H  
 Báscula multifuncionale de plataforma HX7.4C  
 Báscula multifuncional HX7 HR  
 Balanza de alta resolución inoxidables HY10.HRP.H  
 Básculas multifuncionales de patines inoxidables HX7.4P2 H  
 Báscula con rampa Multifuncionale inoxidables HX7.4N H.LD  
 Básculas multifuncionales para paletas inoxidables HX7.4P H  
 Báscula multifuncional HY10  
 Báscula multifuncionale inoxidable HY10 H

Balanza de alta resolución HY10.HRP  
 Báscula multifuncional HX7  
 Báscula multifuncional de plataforma empotrada inoxidable HX7.4 H/Z  
 Báscula multifuncionale de plataforma inoxidable HX7.4 H  
 Básculas multifuncionales de patines HX7.4P2  
 Balanza HY10.H para CCE  
 Terminal de pesaje PUE HX7  
 Terminal de pesaje PUE HY10  
 Básculas multifuncionales para paletas HX7.4P

# Dimensiones de aparato

