



More information on the website
radwag.com/en/info,w1,MP0

PT0439.5 Cable

WX-013-0220



The drawings, photos and graphics used are for illustrative purposes only.

Overview

PT0439 cable is used for connecting PUE 5, PUE HY10, PUE HX7 and PUE H315 stainless steel terminals and indicators via RS 232.

Standard length: 5 m

Compatible with (Additional Fee)

PUE 5 Weighing Terminal
PUE HX7 Weighing Terminal

PUE HY10 Weighing Terminal
PUE H315 Weighing Terminal